



# VEHICLE INSPECTION REPORT

**EF60XKT**

## Ford Focus 1.6 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	24/01/2011	Keys	4	CAP Clean	£1,375.00
Year	2011	Service history	Yes	CAP Average	£970.00
Mileage	97,236 Miles Warranted	Service documents	Service Book	CAP Below	£575.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	Black	Last service date	08/08/2014	Doors	5
VIN	WF0PXXGCDPAP65844	Last service miles	26,395		
Body Style	Hatchback	MOT Due	05/10/2025		

Last Service - 02.08.2014 at 26395 miles (3 services)  
High Clutch Seats Are Stained

### Tyres


NSF	NEXEN	5.7mm
NSR	BUDGET	6.2mm
OSF	BUDGET	Damaged
OSR	KUMHO	Worn
Spare	BUDGET	OK

## Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Front armrest
- ABS
- Traction control
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Alarm
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear headrests
- ESP
- Central locking
- Spare wheel

## Photos






## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Not Thru Paint



2: Door osf  
Scratched  
Over 25mm Thru Paint



No Image



3: Door osr  
Scratched  
Over 25mm Not Thru Paint

4: Door osr  
Chipped  
Edge Chip



5: Door osr  
Dented  
2 Or Less UpTo 10mm

No Image

6: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



7: Bumper Rear  
Poor Previous Repair  
Paint Flake



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Door nsf  
Chipped  
Edge Chip



11: Door nsf  
Scratched  
Over 25mm Not Thru Paint



12: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



13: Bumper Front  
Poor Previous Repair  
Poor Paint



14: Bonnet  
Chipped  
1 To 5



No Image

No Image

15: Bonnet  
Scratched  
Over 25mm Not Thru Paint

16: Roof  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Wheel osr  
Scratched  
Over 50mm



19: Wheel nsr  
Scratched  
Over 50mm



20: Wheel nsf  
Scratched  
Over 50mm

No Image

21: Tyre osf  
Damaged  
Replace

No Image

22: Tyre osr  
Worn  
Replace

No Image

23: Tyre osf  
Damaged  
Replace

No Image

24: Tyre osr  
Worn  
Replace



25: D Post os  
Dented  
Between 10mm + 30mm

No Image

26: Tyre osf  
Damaged  
Replace

No Image

27: Tyre osr  
Worn  
Replace

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK