



VEHICLE INSPECTION REPORT

GU64VRK

Skoda Fabia 1.2 TSI 105 Black Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/12/2014	Keys	2	CAP Clean	£2,125.00
Year	2014	Service history	Yes	CAP Average	£1,700.00
Mileage	106,107 Miles Warranted	Service documents	Printout	CAP Below	£1,275.00
Fuel Type	Petrol	Number of stamps	13	Gearbox	MANUAL
Colour	BLACK	Last service date	25/04/2025	Gears	5
VIN	TMBKN25J7E3139085	Last service miles	104,494		
Body Style	Estate	MOT Due	09/05/2026		

£65 ADDITIONAL FEE. LAST SERVICE 25/4/25 @ 104494 MILES (13 SERVICES 6 MAIN DEALER) PRINT
Misfire
Emi, epc and traction control light on

Tyres

NSF	BUDGET	4.0mm
NSR	NEXEN	2.0mm
OSF	BUDGET	4.0mm
OSR	NEXEN	3.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- ABS
- Remote central locking
- Radio/CD
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Chipped
Multiple Chips




8: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Dented
Between 10mm + 30mm




14: Qtr Panel osr
Rusted
UpTo 5mm



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Chipped
1 To 5



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Chipped
1 To 5



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Scratched
UpTo 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK