



VEHICLE INSPECTION REPORT

YN13LBY

Volvo V40 D2 R DESIGN 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	12/03/2013	Keys	2	CAP Clean	£2,075.00
Year	2013	Service history	Yes	CAP Average	£1,650.00
Mileage	133,298 Miles Warranted	Service documents	Printout	CAP Below	£1,250.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	MANUAL
Colour	RED	Last service date	30/09/2021	Gears	6
VIN	YV1MV8461D2032645	Last service miles	99,350	Doors	5
Body Style	Hatchback	MOT Due	26/03/2026		

£100 ADDITIONAL FEE LAST SERVICE 30/9/21 @ 99350 MILES (1 SERVICE) PRINT
CLUTCH REPLACED 31/3/23 @ 117342 MILES Abs light on, traction control light on

Tyres		
NSF	BUDGET	3.0mm
NSR	MICHELIN	5.0mm
OSF	LAUFENN	3.0mm
OSR	BOTO	5.0mm
Spare		

Features


- Bluetooth connection
- Internet connection
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Solid Paint
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Between 10mm + 30mm




5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
Over 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: B Post os
Dented
Between 10mm + 30mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Poor Previous Repair
Poor Colour



17: Roof Lining
Scuffed
Over 25mm



18: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK