

VEHICLE INSPECTION REPORT

AJ09UEB

Peugeot 107 1.0 Verve 5dr

Inspection		venicie			nama	
Serious Damage?	No	VAT	Margin		Grade	
		V5	TBC			
Details						
Reg. date	15/06/2009	VIN	VF3PNCFAC88361938	CAP Below	£250.00	
Year	2009	Body Style	Hatchback	Gearbox	MANUAL	_
Mileage	77,618 Miles Not Warranted	Keys	2	Doors	5	_
		CAP Clean	£1,050.00			_
Fuel Type	Petrol	CAP Average	£660.00			
Colour	Orange					

Engine rattling and possible exhaust leak Clutch issue

Tyres

NSF	AUTOGREEN	4.0mm	
NSR	PIRELLI	5.0mm	
OSF	AUTOGREEN	5.0mm	
OSR	HANKOOK	4.0mm	
Spare			

Features

- PAS
- · Air conditioning
- Rear headrests
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Climate control Steering wheel rake adjustment Passenger airbag
- Alloy wheels
- Radio/CD
- Front electric windowsMetallic Paint
- Central locking
- Body coloured bumpers
- Front head restraints
- · Remote central locking

Photos























Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Wing nsf Chipped 1 To 5



4: Wheel nsf Scratched Over 50mm



5: Door nsf Dented Over 30mm



6: Door nsr Dented Over 30mm




7: Wheel nsr Scratched Over 50mm



8: Bumper Rear Scratched Over 100mm Thru Paint



9: Wheel osr Scratched Over 50mm



10: Door osr Chipped 1 To 5



11: Door osf Scratched Over 25mm Thru Paint



12: Sill os Dented With Paint Damage



13: Wing osf Scratched Over 25mm Thru Paint



14: Wheel osf Scratched Over 50mm

Interior

Carpet Condition Seat Condition

Average Average Upholstery Condition Odour

Average No