



VEHICLE INSPECTION REPORT

LD19FKL

Ford Focus 1.0 EcoBoost 125 Titanium 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|----------------|
| Serious Damage? | No | VAT | VAT Qualifying |
| | | V5 | TBC |



Details

| | | | | | |
|-----------|---------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 02/04/2019 | VIN | WF0NXXGCHNKK45948 | CAP Average | £5,600.00 |
| Year | 2019 | Body Style | Hatchback | CAP Below | £4,725.00 |
| Mileage | 77,291 Miles Warranted | Keys | 1 | Gearbox | MANUAL |
| Fuel Type | Petrol | MOT Due | 31/01/2026 | Gears | 6 |
| Colour | BLACK | CAP Clean | £6,450.00 | Doors | 5 |

Eml light is on

Tyres

| | | |
|-------|----------|-------|
| NSF | BUDGET | 4.0mm |
| NSR | KORMORAN | 5.0mm |
| OSF | SAILUN | 5.0mm |
| OSR | KORMORAN | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Wheel osf
Scratched
Over 50mm



3: Door osf
Chipped
Edge Chip



4: Door osr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Dented
Between 10mm + 30mm



6: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



7: Bumper Rear
Hole
UpTo 25mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Door nsr
Dented
Between 10mm + 30mm



13: Door nsf
Scratched
Over 25mm Not Thru Paint




14: Wheel nsf
Scratched
Up To 50mm




15: Wing nsf
Scratched
Over 25mm Not Thru Paint



16: Bumper Front
Chipped
Multiple Chips



17: Bonnet
Chipped
1 To 5



18: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

| | | | |
|----------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|--------------------------|-------|-------------------------------------|----|
| EML light illuminated | Fault | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |