



VEHICLE INSPECTION REPORT

SM62XLG

Vauxhall Antara 2.2 CDTi Exclusiv 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/01/2013	Body Style	Hatchback	Last service miles	53,974
Year	2013	Keys	1	MOT Due	Expired
Mileage	66,803 Miles Not Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Doors	5
Colour	Grey	Number of stamps	10		
VIN	W0LLH6EH5CB094990	Last service date	12/10/2023		

Last Service: 12/10/2023 at 53974 miles. (10 services (3 main dealer)). Book & print. Intermittent engine vibration and osr window fault

Tyres

NSF	HANKOOK	2.0mm
NSR	HIFLY	5.0mm
OSF	RIKEN	2.0mm
OSR	HIFLY	5.0mm
Spare		

Features


- Front parking sensor
- Steering wheel mounted controls
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Trip computer
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Audio remote control
- Front fog lights
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Radio/CD
- Full size spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Boot Lid
Chipped
1 To 5



2: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



4: Wheel nsr
Scratched
Up To 50mm




5: Door nsr
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Screen Front
Chipped
UpTo 10mm



9: Wing nsf
Chipped
1 To 5



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bumper Front
Scratched
Over 25mm Not Thru Paint



12: Wing osf
Chipped
1 To 5



13: Wheel nsf
Scratched
Up To 50mm



14: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



15: Door osf
Dented
Over 2 UpTo 10mm



16: Door osr
Dented
Between 10mm + 30mm



17: Wheel osr
Scratched
Up To 50mm



18: Switches And Controls
Broken
Replace



19: Door Pad osf
Scuffed
Over 25mm



20: Bonnet
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
		Steering	OK