



VEHICLE INSPECTION REPORT

FV65NWX

Nissan Juke 1.5 dCi N-Connecta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	10/12/2015	Keys	2	CAP Clean	£2,350.00
Year	2015	Service history	Yes	CAP Average	£1,900.00
Mileage	116,878 Miles Warranted	Service documents	Service Book	CAP Below	£1,400.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	MANUAL
Colour	GREY	Last service date	06/12/2024	Gears	6
VIN	SJNFCAF15U7175629	Last service miles	109,060	Doors	5
Body Style	Hatchback	MOT Due	09/12/2025		

LAST SERVICE 6/12/24 @ 109060 MILES (8 SERVICES 4 MAIN DEALER) BOOK AND PRINT Engine noisy

Tyres

NSF	AUTOGREEN	4.0mm
NSR	AUTOGREEN	4.0mm
OSF	AUTOGREEN	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint




13: Qtr Panel osr
Chipped
1 To 5



14: Wheel osr
Scratched
Up To 50mm




15: Door osr
Chipped
1 To 5



16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
1 To 5



18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Wheel osf
Scratched
Up To 50mm



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK