

VEHICLE INSPECTION REPORT

HV14WLK

Nissan Note 1.2 Acenta Premium 5dr [Comfort Pack]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present	_	
Details					
Reg. date	31/03/2014	Keys	2	CAP Clean	£2,525.00
Year	2014	Service history	Yes	CAP Average	£2,050.00
Mileage	61,042 Miles Warranted	Service documents	Electronic / Online	CAP Below	£1,600.00
		Number of stamps	4	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	07/10/2024	Gears	5
Colour	WHITE	Last service miles	53,015		
VIN	SJNTAAE12U1000445	MOT Due	20/10/2025		
Body Style	MPV			<u> </u>	

£100 ADDITIONAL FEE

Last Service - 07.10.2024 at 53015 miles (4 services confirmed) Eml light is on, steering knocking, engine misfires

Tyres

NSF	BUDGET	5.0mm	
NSR	OVATION	5.0mm	
OSF	BUDGET	5.0mm	_
OSR	OVATION		
Spare			_

Features

- Bluetooth connection
- Rear wiper
- Fixed panoramic glass roofFront head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- · Cruise control
- Digital radio
- Air conditioning
 Height adjustable drivers seat
- 3x3 point rear seat belts Passenger airbag
- Cloth seat trim
- Navigation system
- Body coloured bumpers Folding rear seats Rear electric windows
- ABS
- Side airbags
- Alloy wheels

- PAS
- Electric door mirrors
- Front electric windows Rear headrests

- Drivers airbagCentral locking

Photos










Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips



3: Wheel osf Scratched Over 50mm



4: Wing nsf Chipped 1 To 5



5: Door nsf Dented 2 Or Less UpTo 10mm



6: Door nsr Scratched Over 25mm Thru Paint



7: Qtr Panel nsr Chipped Edge Chip



8: Bumper Rear Dented With Paint Damage



9: Tailgate Chipped 1 To 5



10: Qtr Panel osr Dented Between 10mm + 30mm



11: Door osr Chipped Edge Chip



12: Door osf Chipped 1 To 5



13: Wheel osf Scratched Up To 50mm



14: Fascia Panel Broken Replace

Interior

Carpet Condition Seat Condition

Average Poor **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	K Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	Fault