



VEHICLE INSPECTION REPORT

AF70CWJ

MG Mg Zs EXCLUSIVE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	12/01/2021	Keys	1	CAP Clean	£5,825.00
Year	2021	Service history	Yes	CAP Average	£5,050.00
Mileage	94,264 Miles Warranted	Service documents	Printout	CAP Below	£4,275.00
Fuel Type	Electric	Number of stamps	3	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	24/06/2022	Gears	1
VIN	SDPW7CB3FLZ179241	Last service miles	30,999	Doors	5
Body Style	Hatchback	MOT Due	11/01/2026		

£65 ADDITIONAL FEE.

Last service 24/06/2022 at 30999 miles (3 main dealer services).

Tyres



NSF	SAILUN	Illegal
NSR	SAILUN	2.0mm
OSF	SAILUN	2.0mm
OSR	SUNNY	2.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Solid Paint
- ESP
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

No Image


3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Scratched
Up To 50mm

6: Door osr
Chipped
1 To 5



7: Door osf
Dented
Over 30mm


8: Wing osf
Chipped
1 To 5



9: Wheel osf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bumper Front
Scratched
Over 25mm Not Thru Paint



12: Bonnet
Chipped
1 To 5




13: Wheel nsf
Scratched
Up To 50mm



14: Wing nsf
Scratched
Over 25mm Not Thru Paint



15: Wheel nsr
Scratched
Up To 50mm



16: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



17: Seat Base Cover osf
Torn
Over 3mm



18: Screen Front
Chipped
UpTo 10mm



19: Door nsf
Dented
With Paint Damage



20: Door nsr
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		