

### **VEHICLE INSPECTION REPORT**



### **Renault ZOE DYNAMIQUE INTENS**

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape
		V5	Present		
Details					
Reg. date	30/09/2014	Body Style	Hatchback	Last service miles	33,755
Year	2014	Keys	2	MOT Due	29/09/2025
Mileage	35,222 Miles Warranted	Service history	Yes	CAP Clean	£1,500.00
		Service documents	Service Book	CAP Average	£1,175.00
Fuel Type	ELECTRICITY	Number of stamps	9	CAP Below	£875.00
Colour	BLACK	Last service date	12/09/2024	Doors	5
VIN	VF1AGVYA049572610				,

### BATTERY LEASE LAST SERVICE 12/9/24 @ 33755 MILES (9 MAIN DEALER) BOOK CHARGING CABLES **MISSING**

Tyres
-------

NSF	BUDGET	2.0mm	
NSR	BUDGET	4.0mm	_
OSF	BUDGET	4.0mm	
OSR	BUDGET	4.0mm	
Spare			

### **Features**

- Bluetooth connection
- PAS
- Audio remote control
- · Air conditioning
- Front head restraints
- Metallic Paint
- · Isofix child seat anchor points
- · Remote central locking
- Cruise control
- Rear parking sensor Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- · Alloy wheels

- · Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

### **Photos**











## **Condition Check**



### **Damage Photos**



1: Bonnet Dented With Paint Damage



2: Bumper Front Chipped Multiple Chips

## No Image


3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

## No Image

5: Wing nsf Scratched Over 25mm Not Thru Paint



6: Door nsf Chipped 1 To 5

# No Image

7: Door nsf Scratched Over 25mm Not Thru Paint



8: Door nsr Dented 2 Or Less UpTo 10mm

## No Image

9: Door nsr Scratched Over 25mm Not Thru Paint



10: Wheel nsrScratchedUp To 50mm

# No Image

11: Qtr Panel nsrScratchedOver 25mm Not Thru Paint



12: Bumper Rear Poor Previous Repair Poor Paint



13: Boot Lid Dented 2 Or Less UpTo 10mm

# No Image

14: Qtr Panel osr Scratched Over 25mm Not Thru Paint



15: Wheel osr Scratched Up To 50mm



16: Door osr Dented Over 2 UpTo 10mm



17: Door osf Dented With Paint Damage

# No Image

18: Wing osf Scratched Over 25mm Not Thru Paint



19: Wheel osf Scratched Up To 50mm

#### Interior

**Carpet Condition Upholstery Condition** Average **Seat Condition** Odour Average

Average No

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK