



VEHICLE INSPECTION REPORT

MC14NRZ

Peugeot 108 1.2 VTi Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	16/08/2014	Keys	2	CAP Clean	£2,525.00
Year	2014	Service history	Yes	CAP Average	£2,075.00
Mileage	46,564 Miles Warranted	Service documents	Service Book	CAP Below	£1,625.00
Fuel Type	PETROL	Number of stamps	8	Gearbox	MANUAL
Colour	MAUVE/PURPLE	Last service date	29/11/2024	Gears	5
VIN	VF3PAHMTBER253931	Last service miles	44,042	Doors	5
Body Style	Hatchback	MOT Due	06/12/2025		

LAST SERVICE 29/11/24 @ 44042 MILES (8 SERVICES 2 MAIN DEALER) BOOK Tapping/ vibration from engine

Tyres




NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- ABS
- Passenger airbag
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Curtain airbags
- Central locking
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Wheel osr
Scratched
Over 50mm

No Image


13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

No Image


14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK