



VEHICLE INSPECTION REPORT

SA15UZP

Peugeot 108 1.0 Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/04/2015	Keys	2	CAP Clean	£2,000.00
Year	2015	Service history	Yes	CAP Average	£1,600.00
Mileage	96,130 Miles Warranted	Service documents	Service Book	CAP Below	£1,175.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	BLUE	Last service date	13/08/2019	Gears	5
VIN	VF3PSCFBBER047712	Last service miles	38,528	Doors	5
Body Style	Hatchback	MOT Due	26/11/2025		

Last service 13/08/2019 at 38,528 miles- 4 services (3 MAIN DEALER)

Tyres


NSF	HANKOOK	3.0mm
NSR	CONTINENTAL	4.0mm
OSF	HANKOOK	3.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Front head restraints
- ABS
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Height adjustable drivers seat
- Curtain airbags
- Traction control
- Steel wheels
- Steering wheel mounted controls
- Air conditioning
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Poor Previous Repair
Poor Paint




4: Door nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Chipped
1 To 5




7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel nsr
Rusted
UpTo 5mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osr
Dented
Between 10mm + 30mm




14: Door osf
Dented
Over 2 UpTo 10mm



15: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



16: Wing osf
Chipped
1 To 5



17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Other
N/A
N/A



19: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK