



# VEHICLE INSPECTION REPORT

**GV61NPE**

## Peugeot 207 1.4 VTi 95 Active 5dr

Cat: D

### Inspection

Serious Damage? No

### Vehicle

VAT Margin  
V5 Present

nama  
GRADE  
**5**

### Details

Reg. date	31/01/2012	Keys	1	CAP Clean	£840.00
Year	2012	Service history	Yes	CAP Average	£430.00
Mileage	53,507 Miles Warranted	Service documents	Printout	CAP Below	£225.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	BLUE	Last service date	21/02/2025	Gears	5
VIN	VF3WC8FP0CW010106	Last service miles	52,353	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£65 ADDITIONAL FEE. LAST SERVICE 21/2/25 @ 52353 MILES (8 SERVICE) PRINT  
Category D Insurance Loss. Vehicle Damaged But Repairable - Insurer Decided Not To Repair.

### Tyres

NSF	TIGAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	POWERTRAC	5.0mm

### Spare

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Lane departure warning
- Cloth seat trim
- Rear wiper
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Rusted  
Over 5mm



4: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



5: Door nsf  
Dented  
Over 30mm



6: Aperture Seal nsr  
Broken  
Replace



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Tailgate  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Door osr  
Dented  
With Paint Damage



13: Door osf  
Chipped  
Multiple Chips



14: Wing osf  
Dented  
With Paint Damage





15: Roof  
Rusted  
Over 5mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK