



VEHICLE INSPECTION REPORT

SY60RZJ

Audi A3 2.0 TDI 170 Sport 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/09/2010	Keys	1	CAP Clean	£2,000.00
Year	2010	Service history	Yes	CAP Average	£1,575.00
Mileage	112,952 Miles Warranted	Service documents	Service Book	CAP Below	£1,125.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	SEMI AUTO
Colour	GREY	Last service date	06/05/2022	Gears	6
VIN	WAUZZZ8PXAA118665	Last service miles	112,949	Doors	5
Body Style	Hatchback	MOT Due	10/09/2025		

Last service 06/05/2022 at 112,949 miles- 9 services (1 main dealer) Smoking

Tyres


NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Audio remote control
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Rusted
Over 5mm



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
2 Or Less UpTo 10mm



8: Door nsr
Chipped
1 To 5



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm




11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
UpTo 25mm Thru Paint



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Poor Previous Repair
Poor Paint




16: Wheel osr
Scratched
Over 50mm



17: Door osr
Poor Previous Repair
Poor Paint



18: Door osf
Chipped
1 To 5




19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Rusted
Over 5mm



21: Wheel of
Scratched
Over 50mm



22: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK