



VEHICLE INSPECTION REPORT

YC60BSX

Nissan Qashqai 1.6 [117] N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/10/2010	Keys	2	CAP Clean	£1,900.00
Year	2010	Service history	Yes	CAP Average	£1,475.00
Mileage	80,228 Miles Warranted	Service documents	Service Book	CAP Below	£1,025.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	BLACK	Last service date	14/01/2022	Gears	6
VIN	SJNFAAJ10U2155532	Last service miles	46,700	Doors	5
Body Style	Hatchback	MOT Due	18/01/2026		

£65 ADDITIONAL FEE. LAST SERVICE 14/1/22 @ 46700 MILES (10 SERVICES 4 MAIN DEALER) BOOK
Gearbox noise

Tyres


NSF	SUNNY	2.0mm
NSR	SUNNY	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image



10: Qtr Panel Arch Extension ns
Broken
Replace



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Cracked
Over 25mm



13: Boot Lid
Dented
Over 30mm



14: Wheel nsr
Scratched
Over 50mm




15: Qtr Panel osr
Chipped
1 To 5



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Chipped
1 To 5



18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Dented
Between 10mm + 30mm



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		