



VEHICLE INSPECTION REPORT

GV12LOJ

Ford Fiesta 1.25 Zetec 5dr [82]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2012	Keys	1	CAP Clean	£1,175.00
Year	2012	Service history	Yes	CAP Average	£770.00
Mileage	125,016 Miles Warranted	Service documents	Service Book	CAP Below	£375.00
Fuel Type	Petrol	Number of stamps	11	Gearbox	MANUAL
Colour	BLACK	Last service date	22/07/2025	Gears	5
VIN	WF0JXXGAJJCK83032	Last service miles	124,787	Doors	5
Body Style	Hatchback	MOT Due	29/07/2026		

LAST SERVICE 22/7/25 @ 124787 MILES (11 SERVICES 7 MAIN DEALER) BOOK AND PRINT

Tyres

NSF	SAILUN	5.0mm
NSR	BUDGET	5.0mm
OSF	SAILUN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- ESP
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate
Chipped
1 To 5



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Wheel osr
Scratched
Up To 50mm



14: Door osr
Dented
Over 30mm



15: Sill os
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
Over 30mm



17: Roof
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Wing nsf
Chipped
1 To 5



20: Carpets Front
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK