



VEHICLE INSPECTION REPORT

AO15MXE

Smart Forfour 0.9 Turbo Prime Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/04/2015	Keys	2	CAP Clean	£1,750.00
Year	2015	Service history	Yes	CAP Average	£1,350.00
Mileage	153,062 Miles Warranted	Service documents	Printout	CAP Below	£950.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	WHITE	Last service date	23/12/2024	Gears	5
VIN	WME4530442Y028590	Last service miles	146,893	Doors	5
Body Style	Hatchback	MOT Due	10/04/2026		

Last service 23/12/2024 at 146,893 miles- 12 services (6 main dealer) Vibration at idle/ rough idle

Tyres

NSF	MICHELIN	3.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
 - Rear wiper
 - Body coloured bumpers
 - Climate control
 - Rear headrests
 - Isofix child seat anchor points
 - Remote central locking
- Cruise control
 - Steering wheel mounted controls
 - Electric door mirrors
 - Front electric windows
 - Solid Paint
 - Passenger airbag
 - Leather seat trim
- PAS
 - Audio remote control
 - Fixed panoramic glass roof
 - Front head restraints
 - ABS
 - Tyre pressure monitor
 - Alloy wheels
- Rear parking sensor
 - Digital radio
 - Air conditioning
 - Height adjustable drivers seat
 - Drivers airbag
 - Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
Over 2 UpTo 10mm

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Dented
Over 30mm



15: Wheel osr
Scratched
Over 50mm

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Dented
2 Or Less UpTo 10mm

No Image

18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: A Post os
Chipped
Multiple Chips



23: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK