



VEHICLE INSPECTION REPORT

BV14MHJ

Skoda Superb 2.0 TDI CR 140 Elegance 5dr DSG

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	24/03/2014	Keys	1	CAP Clean	£2,100.00
Year	2014	Service history	Yes	CAP Average	£1,650.00
Mileage	184,165 Miles Warranted	Service documents	Printout	CAP Below	£1,225.00
Fuel Type	Diesel	Number of stamps	3	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	24/11/2017	Gears	6
VIN	TMBKE73T2E9039992	Last service miles	54,505		
Body Style	Estate	MOT Due	25/03/2026		

£65 ADDITIONAL FEE LAST SERVICE 24/11/17 @ 54505 MILES (3 MAIN DEALER) PRINT Suspension knock

Tyres

NSF	RAPID	2.0mm
NSR	BUDGET	3.0mm
OSF	NEXEN	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Navigation system
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Scratched
UpTo 25mm Thru Paint

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint




9: Sill ns
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm




11: Qtr Panel nsr
Chipped
1 To 5



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Chipped
1 To 5



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Over 2 UpTo 10mm



19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Chipped
1 To 5

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Wing osf
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Seat Back Cover osf
Torn
UpTo 3mm



25: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK