



VEHICLE INSPECTION REPORT

VO65MVX

Vauxhall Insignia 1.6 CDTi SRi Vx-line Nav 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	24/11/2015	Keys	3	CAP Clean	£3,075.00
Year	2015	Service history	Yes	CAP Average	£2,550.00
Mileage	84,721 Miles Warranted	Service documents	Printout	CAP Below	£2,025.00
Fuel Type	Diesel	Number of stamps	3	Gearbox	MANUAL
Colour	White	Last service date	31/08/2024	Doors	5
VIN	W0LGS6E32G1030926	Last service miles	79,397		
Body Style	Hatchback	MOT Due	30/08/2025		

Last Service - 31.08.2024 at 79397 miles (3 services)

Tyres

NSF	RAPID	3.0mm
NSR	RAPID	5.0mm
OSF	RAPID	3.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Electric door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Rear airbags
- Central locking
- Cruise control
- Rear parking sensor
- Auxiliary input socket
- Front fog lights
- Front electric windows
- Rear electric windows
- Solid Paint
- ESP
- Side airbags
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Radio/CD
- Air conditioning
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Leather seat trim
- Heated front seat
- Trip computer
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Alarm
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Rippled Over 30%



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Wing osf
Chipped
1 To 5



5: Door osf
Chipped
1 To 5



6: Door osr
Chipped
1 To 5



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Boot Lid
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Door nsf
Dented
Between 10mm + 30mm



13: Wing nsf
Chipped
1 To 5



14: Wheel nsf
Scratched
Over 50mm



15: Wheel nsr
Scratched
Over 50mm



16: Wheel osr
Scratched
Over 50mm



17: Wheel osf
Scratched
Over 50mm



18: Seat Base Cover osf
Torn
Over 3mm



19: Sill os
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK