



VEHICLE INSPECTION REPORT

GU13YLB

Nissan Juke 1.6 Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/05/2013	Keys	2	CAP Clean	£2,875.00
Year	2013	Service history	Yes	CAP Average	£2,425.00
Mileage	59,336 Miles Warranted	Service documents	Service Book	CAP Below	£1,950.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	SILVER	Last service date	25/09/2024	Gears	5
VIN	SJNFBAF15U6376589	Last service miles	54,103	Doors	5
Body Style	Hatchback	MOT Due	05/10/2025		

Last Service - 25.09.2024 at 54103 miles (10 main dealer services)

Tyres

NSF	LAUFENN	5.0mm
NSR	BUDGET	5.0mm
OSF	LAUFENN	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Screen Front
Chipped
Over 10mm



6: Door nsf
Dented
Over 30mm



7: Door osr
Scratched
Over 25mm Thru Paint



8: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
2 Or Less UpTo 10mm



14: Door osf
Dented
With Paint Damage



15: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK