



VEHICLE INSPECTION REPORT

LV09DHC

Renault Clio 1.5 dCi 86 Dynamique S 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/03/2009	Keys	2	CAP Clean	£720.00
Year	2009	Service history	Yes	CAP Average	£340.00
Mileage	86,445 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	MANUAL
Colour	BLUE	Last service date	18/12/2023	Gears	5
VIN	VF1BRCF0H41010869	Last service miles	82,261	Doors	5
Body Style	Hatchback	MOT Due	04/01/2026		

Last service 18/12/2023 at 82261 miles (1 service) Electronic fault on dash

Tyres



NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Service indicator
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Poor Previous Repair
Poor Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
1 To 5

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Dented
Over 30mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Poor Previous Repair
Poor Paint



13: Boot Lid
Dented
With Paint Damage



14: Qtr Panel osr
Dented
Between 10mm + 30mm

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Over 50mm




17: Door osr
Dented
With Paint Damage



18: Door osf
Chipped
1 To 5

No Image




19: Door osf
Scratched
Over 25mm Not Thru Paint

20: Wing osf
Scratched
UpTo 25mm Thru Paint



21: Wing osf
Scratched
UpTo 25mm Thru Paint



22: Wing osf
Scratched
Over 25mm Not Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Seat Base Cover osf
Torn
UpTo 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK