



VEHICLE INSPECTION REPORT

GU59YLA

Toyota IQ 1.0 VVT-i 3dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 29/09/2009

Year 2009

Mileage 39,389 Miles
Warranted

Fuel Type Petrol

Colour WHITE

VIN JTNML11020J043483

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 12

Last service date 14/06/2025

Last service miles 36,461

MOT Due 29/09/2025

CAP Clean £1,900.00

CAP Average £1,475.00

CAP Below £1,100.00

Gearbox MANUAL

Gears 5

Doors 3

Last Service - 14.06.2024 at 36461 miles (12 main dealer services)

Tyres

NSF FALKEN 4.0mm

NSR BUDGET 4.0mm

OSF FALKEN 3.0mm

OSR HANKOOK 4.0mm


Spare

Features


- PAS
- Radio/CD
- Climate control
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Curtain airbags
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
1 To 5




3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Cracked
Over 25mm




5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Not Thru Paint




9: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Chipped
Multiple Chips



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

No Image

No Image

15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Up To 50mm

19: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |