



# VEHICLE INSPECTION REPORT

EO66TKJ

## Volkswagen UP 1.0 High Up 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
3

### Details

Reg. date	28/10/2016	Keys	2	CAP Clean	£4,900.00
Year	2016	Service history	Yes	CAP Average	£4,175.00
Mileage	44,000 Miles Warranted	Service documents	Service Book	CAP Below	£3,475.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	BLUE	Last service date	26/10/2022	Gears	5
VIN	WVWZZZAAZHD010046	Last service miles	24,283	Doors	3
Body Style	Hatchback	MOT Due	27/10/2025		

Last service 26/10/2022 at 24283 miles (5 services (4 main dealer)).

### Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel osf  
Scratched  
Over 50mm



5: Wing osf  
Dented  
Over 30mm



6: Door osf  
Chipped  
1 To 5



7: Qtr Panel osr  
Dented  
Between 10mm + 30mm



8: Wheel osr  
Scratched  
Over 50mm



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



12: Wheel nsr  
Scratched  
Over 50mm



13: Door nsf  
Dented  
Over 2 UpTo 10mm



14: Wing nsf  
Dented  
With Paint Damage



15: Wheel nsf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK