



VEHICLE INSPECTION REPORT

HF65RXC

Nissan Note 1.2 Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	14/09/2015	Keys	2	CAP Clean	£2,050.00
Year	2015	Service history	Yes	CAP Average	£1,600.00
Mileage	91,526 Miles Warranted	Service documents	Service Book	CAP Below	£1,175.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLUE	Last service date	20/09/2018	Gears	5
VIN	SJNTAAE12U1126805	Last service miles	27,591		
Body Style	MPV	MOT Due	28/09/2025		

Last service 20/09/2018 at 27591 miles (2 main dealer services). Knocking exhaust

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Roof
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Tailgate
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
With Paint Damage



14: Wing osf
Chipped
1 To 5



15: Wheel of
Scratched
Over 50mm



16: Carpets Front
Scuffed
Over 25mm



17: Seat Base Cover of
Scuffed
Over 25mm

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK