



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY66NXA

Mazda CX-3 2.0 Sport Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2016	Body Style	Hatchback	MOT Due	29/11/2025
Year	2016	Keys	2	CAP Clean	£7,300.00
Mileage	53,012 Miles Warranted	Service history	Yes	CAP Average	£6,400.00
Fuel Type	Petrol	Service documents	Printout	CAP Below	£5,500.00
Colour	Red	Last service date	13/11/2024	Gearbox	MANUAL
VIN	MMZDK6W761W116861	Last service miles	49,641	Doors	5

£65 ADDITIONAL FEE Last service 13/11/2024 @ 49641 miles (5 SERVICES)

Tyres

NSF	GOODYEAR	3.0mm
NSR	TOYO	4.0mm
OSF	GOODYEAR	4.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Telephone
- Air conditioning
- Metallic Paint
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Radio/CD
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Rear headrests
- ESP
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
Over 25mm Not Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Poor Previous Repair
Poor Paint



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Chipped
Edge Chip



10: Wheel nsr
Scratched
Over 50mm



11: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Wing nsf
Scratched
UpTo 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Flasher Side Repeater ns
Broken
Replace



15: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK