



# VEHICLE INSPECTION REPORT

**PO63VFW**

## Nissan Qashqai 1.5 dCi [110] 360 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



### Details

Reg. date	02/09/2013	VIN	SJNFCAJ10U2853025	CAP Average	£1,800.00
Year	2013	Body Style	Hatchback	CAP Below	£1,375.00
Mileage	74,331 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	20/12/2025	Gears	6
Colour	WHITE	CAP Clean	£2,250.00	Doors	5

Copy of part V5. No service history.


Tyres		
NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Poor Previous Repair  
Poor Colour





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Door nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



9: Bumper Rear  
Poor Previous Repair  
Poor Paint



10: Boot Lid  
Poor Previous Repair  
Poor Paint



11: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Poor Previous Repair  
Poor Paint



14: Door osf  
Poor Previous Repair  
Poor Paint





15: Wing of  
Poor Previous Repair  
Poor Paint



16: Wheel of  
Scratched  
Over 50mm



17: Screen Front  
Chipped  
Up To 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		