



VEHICLE INSPECTION REPORT

RV66LOF

Nissan Juke 1.2 DiG-T Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/10/2016	Body Style	Hatchback	CAP Clean	£1,700.00
Year	2016	Keys	1	CAP Average	£1,300.00
Mileage	134,355 Miles Warranted	Service history	Yes	CAP Below	£900.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	WHITE	Last service date	12/06/2025	Gears	6
VIN	SJNFEAF15U7283846	MOT Due	24/10/2025	Doors	5

Services confirmed by Invincible MOT & Repair.
Last service 12/06/2025 - mileage not recorded. (8 services).

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Dented
With Paint Damage



10: Tailgate
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
Between 10mm + 30mm



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Roof
Chipped
Multiple Chips

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK