



VEHICLE INSPECTION REPORT

HN62UYO

Toyota Verso 2.0 D-4D Icon 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/01/2013	Keys	2	CAP Clean	£2,800.00
Year	2013	Service history	Yes	CAP Average	£2,300.00
Mileage	83,282 Miles Warranted	Service documents	Printout	CAP Below	£1,800.00
Fuel Type	Diesel	Number of stamps	3	Gearbox	MANUAL
Colour	RED	Last service date	14/10/2024	Gears	6
VIN	NMTDD26R70R078701	Last service miles	78,502		
Body Style	MPV	MOT Due	02/11/2025		

£100 ADDITIONAL FEE. LAST SERVICE 14/10/24 @ 78502 MILES (3 SERVICES) PRINT

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	5.0mm
OSF	AUTOGREEN	3.0mm
OSR	BUDGET	Illegal
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Scratched
Up To 50mm

No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Chipped
1 To 5

No Image


8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Lamp nsr
Broken
Replace



15: Boot Lid
Dented
Over 30mm



16: Lamp osr
Broken
Replace




17: Qtr Panel osr
Chipped
1 To 5



18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



19: Wheel osr
Scratched
Over 50mm



20: Door osr
Chipped
1 To 5

No Image



21: Door osr
Scratched
Over 25mm Not Thru Paint

22: Door osf
Chipped
1 To 5

No Image



23: Door osf
Scratched
Over 25mm Not Thru Paint

24: Screen Front
Chipped
UpTo 10mm

No Image



25: Wing osf
Scratched
Over 25mm Not Thru Paint

26: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK