



VEHICLE INSPECTION REPORT

MC07ZGE

Volvo XC70 2.4 D5 SE 5dr Geartronic [185]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/03/2007	Keys	2	CAP Clean	£1,850.00
Year	2007	Service history	Yes	CAP Average	£1,450.00
Mileage	121,331 Miles Warranted	Service documents	Printout	CAP Below	£1,050.00
Fuel Type	Diesel	Number of stamps	13	Gearbox	AUTOMATIC
Colour	GREY	Last service date	08/12/2024	Gears	6
VIN	YV1SZ714671258770	Last service miles	115,284		
Body Style	Estate	MOT Due	10/11/2025		

£65 ADDITIONAL FEE. LAST SERVICE 8/12/24 @ 115,284 MILES (13 SERVICES 11 MAIN DEALER) PRINT

Tyres

NSF	AVON	2.0mm
NSR	PIRELLI	Worn
OSF	AVON	2.0mm
OSR	PIRELLI	Worn
Spare		

Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- ESP
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing nsf
Chipped
1 To 5



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Over 50mm



9: Wheel nsf
Scratched
Over 50mm



10: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



12: Door osr
Dented
Over 30mm



13: Door osf
Poor Previous Repair
Poor Paint




14: Wing osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm




16: Wheel osr
Scratched
Over 50mm



17: Tyre nsr
Worn
Replace



18: Tyre osr
Worn
Replace



19: Tyre nsr
Worn
Replace



20: Tyre osr
Worn
Replace

No Image

No Image

21: Tyre nsr
Worn
Replace

22: Tyre osr
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK