

VEHICLE INSPECTION REPORT

GN66WVS

Ford Fiesta 1.0 EcoBoost Titanium 5dr

Inspection Serious Damage? No		Vehicle			nama
		VAT	Margin		Grape Grape
		V5	Present		
Details					
Reg. date	16/09/2016	Keys	2	CAP Clean	£3,100.00
Year	2016	Service history	Yes	CAP Average	£2,600.00
Mileage	63,896 Miles Warranted	Service documents	Service Book	CAP Below	£2,125.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	BLACK	Last service date	10/09/2021	Gears	5
VIN	WF0DXXGAKDGC58823	Last service miles	35,045	Doors	5
Body Style	Hatchback	MOT Due	15/09/2025		

£65 ADDITIONAL FEE.

Last service 10/09/2021 at 35,045 miles- 8 services (4 main dealer)

T	y	re	S
---	---	----	---

NSF	HANKOOK	5.0mm	
NSR	MATADOR	5.0mm	
OSF	MATADOR	5.0mm	
OSR	MATADOR	5.0mm	
Spare			

Features

- Bluetooth connection
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- Front electric windows
- Metallic Paint
 ESP
- Central locking
- Cruise control


- Air conditioning
 Front head restraints
- 3x3 point rear seat belts Isofix child seat anchor points
- · Remote central locking
- PAS
- Radio/CD Climate control
- Height adjustable drivers seat
- ABŠ
- Passenger airbagCloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag Traction control
- · Alloy wheels

Photos










Condition Check



Damage Photos



1: Bumper Rear Chipped Multiple Chips No Image

2: Bumper Rear Scratched Over 25mm Not Thru Paint


No Image

No Image

3: Boot Lid Scratched Over 25mm Not Thru Paint




5: Wheel osr Scratched Over 50mm





6: Door osr Chipped 1 To 5

No Image





8: Door osf Chipped 1 To 5

No Image

9: Door osf Scratched Over 25mm Not Thru Paint



11: Wheel osf Scratched Over 50mm



13: Bumper Front Scratched Over 100mm Thru Paint



Scratched
Over 25mm Thru Paint



12: Bonnet Chipped Multiple Chips



14: Wheel nsf Scratched Over 50mm

No Image

15: Wing nsf Scratched Over 25mm Not Thru Paint



17: Door nsf Chipped 1 To 5



19: Door nsr Chipped 1 To 5



16: Door Mirror Assy nsf Broken Replace

No Image

18: Door nsfScratchedOver 25mm Not Thru Paint

No Image

20: Door nsr Scratched Over 25mm Not Thru Paint



21: Wheel nsr Scratched Over 50mm

No Image

22: Qtr Panel nsr Scratched Over 25mm Not Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK