



# VEHICLE INSPECTION REPORT

**GY55UCO**

## Hyundai Accent 1.6 CDX 5dr Auto

**Cat: N**  
**Inspection**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	03/09/2005	Keys	2	CAP Clean	£760.00
Year	2005	Service history	Yes	CAP Average	£360.00
Mileage	84,739 Miles Warranted	Service documents	Electronic / Online	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	AUTOMATIC
Colour	SILVER	Last service date	02/08/2010	Gears	4
VIN	KMHCH51CR5U271409	Last service miles	41,207	Doors	5
Body Style	Hatchback	MOT Due	01/08/2026		

£65 ADDITIONAL FEE LAST SERVICE 2/8/10 @ 41207 MILES (5 MAIN DEALER) CONFIRMED BY BROOKLYN HYUNDAI

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair.  
Squeaky belt while starting

### Tyres

NSF	ROTALLA	4.0mm
NSR	BUDGET	4.0mm
OSF	ROTALLA	4.0mm
OSR	FULLRUN	4.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Central locking
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Poor Previous Repair  
Rippled Up To 30%



2: Boot Lid  
Scratched  
Over 25mm Not Thru Paint





3: Qtr Panel osr  
Rusted  
Over 5mm



4: Wheel osr  
Scratched  
Over 50mm



5: Door osr  
Chipped  
1 To 5



6: Door osr  
Scratched  
Over 25mm Not Thru Paint



7: Door osf  
Chipped  
1 To 5



8: Sill os  
Rusted  
Over 5mm



9: Wing osf  
Chipped  
1 To 5




10: Wheel osf  
Scratched  
Over 50mm



11: Bonnet  
Poor Previous Repair  
Poor Paint



12: Bumper Front  
Scratched  
25 to 100mm Thru Paint



13: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



14: Wing nsf  
Chipped  
1 To 5



15: Wheel nsf  
Scratched  
Over 50mm




16: Door nsf  
Dented  
Between 10mm + 30mm



17: Sill ns  
Rusted  
Over 5mm



18: Door nsr  
Dented  
Between 10mm + 30mm



19: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK