



VEHICLE INSPECTION REPORT

RJ64FFG

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/12/2014	Keys	2	CAP Clean	£3,150.00
Year	2014	Service history	Yes	CAP Average	£2,625.00
Mileage	132,124 Miles Warranted	Service documents	Printout	CAP Below	£2,125.00
Fuel Type	Diesel	Number of stamps	10	Gearbox	MANUAL
Colour	SILVER	Last service date	14/02/2025	Gears	6
VIN	WVGZZZ5NZFW058733	Last service miles	128,315		
Body Style	Estate	MOT Due	17/12/2025		

£65 ADDITIONAL FEE LAST SERVICE 14/2/25 @ 128315 MILES (10 SERVICES) BOOK AND PRINT Engine knocking

Tyres

NSF	RAPID	5.0mm
NSR	RAPID	5.0mm
OSF	RAPID	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Towbar
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Space saver spare wheel
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint

No Image



3: Bumper Front
Insecure
Action Required

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: A Post ns
Chipped
Over 5mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Dented
Over 30mm



14: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK