



# VEHICLE INSPECTION REPORT

**GF16ZRX**

## Kia Sportage 1.7 CRDi ISG 3 5dr [Sat Nav]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	14/04/2016	VIN	U5YPC815LFL779051	CAP Below	£1,825.00
Year	2016	Body Style	Estate	Gearbox	MANUAL
Mileage	141,622 Miles Warranted	Keys	2	Doors	5
Fuel Type	Diesel	CAP Clean	£2,800.00		
Colour	Silver	CAP Average	£2,300.00		

£65 ADDITIONAL FEE

Tyres		
NSF	BUDGET	6.5mm
NSR	BUDGET	7.9mm
OSF	GOODYEAR	4.7mm
OSR	AVON	6.5mm
Spare	BUDGET	OK

## Features


- Bluetooth connection
- Park assist camera
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Side airbags
- Central locking
- Spare wheel
- Cruise control
- PAS
- Radio/Cassette
- Opening panoramic glass roof
- Front electric windows
- ABS
- Traction control
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Climate control
- Rear headrests
- Passenger airbag
- Alarm
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Not Thru Paint



2: Door osf  
Chipped  
1 To 5




No Image

3: Door osr  
Scratched  
Over 25mm Not Thru Paint



5: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



7: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

No Image

4: Door osf  
Dented  
Over 2 UpTo 10mm




6: Qtr Panel osr  
Chipped  
1 To 5



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Tailgate  
Dented  
Between 10mm + 30mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsr  
Dented  
With Paint Damage




12: Door nsf  
Dented  
With Paint Damage



13: Wing nsf  
Scratched  
Over 25mm Thru Paint



14: Bumper Front  
Cracked  
Over 25mm



15: Bonnet  
Chipped  
1 To 5



16: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		