



VEHICLE INSPECTION REPORT

GU63GKJ

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	24/02/2014	Body Style	Estate	Last service miles	103,096
Year	2014	Keys	2	MOT Due	23/02/2026
Mileage	109,450 Miles Warranted	Service history	Yes	CAP Clean	£4,175.00
Fuel Type	Diesel	Service documents	Printout	CAP Average	£3,525.00
Colour	Silver	Number of stamps	11	CAP Below	£2,925.00
VIN	WVGZZZ5NZEW082259	Last service date	29/11/2024	Gearbox	AUTOMATIC

£65 ADDITIONAL FEE. Cambelt replaced 14/02/2025 @ 107440 miles. Last Service: 29/11/2024 at 103096 miles. (11 services (2 main dealer)) GEARBOX FAULT,EML LIGHT ON

Tyres

NSF	LAUFENN	6.0mm
NSR	BUDGET	3.0mm
OSF	LAUFENN	6.0mm
OSR	LAUFENN	6.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Rear headrests
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Wing osf
Scratched
UpTo 25mm Not Thru Paint



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Poor Previous Repair
Poor Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Tailgate
Dented
With Paint Damage



8: Wheel osr
Scratched
Over 50mm



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsr
Dented
With Paint Damage



11: Door nsf
Dented
Over 30mm



12: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



13: Wing nsf
Dented
Over 30mm




14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Roof
Chipped
1 To 5



18: A Post os
Chipped
1 To 5



19: Wheel nsf
Scratched
Over 50mm



20: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK