



# VEHICLE INSPECTION REPORT

**GV55MWD**

## Volkswagen Polo 1.4 S 75 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/09/2005	Service history	Yes	CAP Average	£290.00
Year	2005	Service documents	Printout	CAP Below	£200.00
Mileage	72,802 Miles Warranted	Number of stamps	1	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	24/08/2007	Gears	5
Colour	RED	Last service miles	8,769	Doors	5
VIN	WVWZZZ9NZ6D031950	MOT Due	09/05/2026		
Body Style	Hatchback	CAP Clean	£680.00		

£65 ADDITIONAL FEE LAST SERVICE 24/8/07 @ 8,769 MILES (1 MAIN DEALER) PRINT oil light flashing when driven

### Tyres


NSF	FALKEN	3.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint



2: Boot Lid  
Chipped  
1 To 5






3: Qtr Panel nsr  
Dented  
With Paint Damage



4: Door nsr  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Chipped  
1 To 5




6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



8: Wing nsf  
Dented  
With Paint Damage



9: Bonnet  
Chipped  
Multiple Chips




10: Bumper Front  
Scratched  
25 to 100mm Thru Paint



11: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



12: Wing osf  
Dented  
Over 2 UpTo 10mm



13: Wing osf  
Scratched  
Over 25mm Not Thru Paint



14: Door osf  
Chipped  
1 To 5

No Image



15: Door osf  
Scratched  
Over 25mm Not Thru Paint

16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Qtr Panel osr  
Dented  
With Paint Damage

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK