



# VEHICLE INSPECTION REPORT

**NU15ZVK**

## Volkswagen UP 1.0 Move Up 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	23/04/2015	Keys	2	CAP Clean	£3,150.00
Year	2015	Service history	Yes	CAP Average	£2,625.00
Mileage	45,758 Miles Warranted	Service documents	Printout	CAP Below	£2,100.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	RED	Last service date	12/01/2021	Gears	5
VIN	WVWZZZAAZFD093732	Last service miles	40,245	Doors	3
Body Style	Hatchback	MOT Due	15/01/2026		

£65 ADDITIONAL FEE LAST SERVICE 12/1/21 @ 40,245 MILES (2 SERVICES 1 MAIN DELAER) PRINT

### Tyres

NSF	BUDGET	4.0mm
NSR	KUMHO	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- PAS
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Remote central locking
- Rear wiper
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- Radio/CD
- Front electric windows
- Solid Paint
- Passenger airbag
- Steel wheels
- Body coloured bumpers
- Front head restraints
- ABS
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint




7: Bumper Rear  
Chipped  
Multiple Chips

No Image

8: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



9: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm




10: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



11: Door osf  
Chipped  
1 To 5



12: Door osf  
Scratched  
Over 25mm Not Thru Paint



13: Wing osf  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK