

# **VEHICLE INSPECTION REPORT**

**GU68CLN** 

## Nissan Leaf 110kW N-Connecta 40kWh 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present		
Details					
Reg. date	01/09/2018	Keys	2	CAP Average	£3,800.00
Year	2018	Service history	Yes	CAP Below	£3,450.00
Mileage	87,562 Miles Warranted	Number of stamps	3	Gearbox	AUTOMATIC
		Last service date	01/04/2025	Gears	1
Fuel Type	Electric	Last service miles	85,839	Doors	5
Colour	SILVER	MOT Due	09/09/2025		
VIN	SJNFAAZE1U0029688	CAP Clean	£4,150.00		
Body Style	Hatchback		, , , , , , , , , , , , , , , , , , , ,		

£65 ADDITIONAL FEE. Services confirmed by Barnard & Brough. Last service 1/4/2025 at 85839 miles. (3 main dealer services). Charging cables in boot.

### **Tyres**

Spare			
OSR	TRIANGLE	6.0mm	
OSF	HANKOOK	3.0mm	
NSR	MATADOR	7.0mm	
NSF	MATADOR	7.0mm	

## **Features**

- Bluetooth connection
- Navigation system
- Rear wiperElectric door mirrors
- Front armrest
- · Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking

- Cruise control
- Park assist camera
- Steering wheel mounted controls Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Air conditioning
- Front head restraintsMetallic Paint
- Drivers airbag
- Rear airbags Partial leather seat trim
- · Heated front seat
- Rear parking sensor Body coloured bumpers Folding rear seats
- Height adjustable drivers seat
  3x3 point rear seat belts
  ESP


- Side airbags
- Alloy wheels

#### **Photos**










# **Condition Check**



# **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Wing nsf Dented Between 10mm + 30mm



4: Wheel nsf Scratched Over 50mm



5: Door nsf Chipped Edge Chip



6: Door nsr Dented Over 30mm



7: Qtr Panel nsr Scratched Over 25mm Thru Paint



8: Wheel nsr Scratched Over 50mm



9: Bumper Rear Scratched Over 100mm Thru Paint



10: Wheel osr Scratched Over 50mm



11: Qtr Panel osr Scratched Over 25mm Thru Paint



12: Door osr Scratched Over 25mm Thru Paint



13: Door osf Chipped Edge Chip




14: Door Mirror Assy osf Scratched (Painted) Over 25mm Thru Paint



15: Wheel osf Scratched Over 50mm



16: Wing osf Dented Between 10mm + 30mm



17: Screen Front Chipped UpTo 10mm



18: Roof Chipped Edge Chip

### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test	
Brakes OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake OK	No Excessive Smoking	OK

EML light illuminated OK		Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	ОК
Sat nav	OK	Steering	OK