



# VEHICLE INSPECTION REPORT

**GU19BKD**

## Skoda Kodiaq 1.5 TSI SE 5dr DSG [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	09/03/2019	Keys	2	CAP Clean	£12,800.00
Year	2019	Service history	Yes	CAP Average	£11,550.00
Mileage	65,436 Miles Warranted	Service documents	Printout	CAP Below	£10,350.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	SEMI AUTO
Colour	BLUE	Last service date	01/07/2020	Gears	7
VIN	TMBKB7NS2K8029574	Last service miles	10,867		
Body Style	Estate	MOT Due	12/06/2026		

£65 ADDITIONAL FEE.

Last service 01/07/2020 at 10867 miles- 1 main dealer service

### Tyres

NSF	KUMHO	5.0mm
NSR	MAXTREK	5.0mm
OSF	DAVANTI	5.0mm
OSR	GENERAL TIRE	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



3: Wheel osr  
Scratched  
Up To 50mm



4: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



5: Door osr  
Dented  
With Paint Damage



6: Door osf  
Dented  
Over 30mm



7: Door Moulding osf  
Missing  
Replace



8: Wing osf  
Scratched  
Over 25mm Thru Paint



9: Wheel osf  
Scratched  
Over 50mm



10: Bonnet  
Chipped  
1 To 5




11: Bumper Front  
Scratched  
Over 100mm Thru Paint



12: Wheel nsf  
Scratched  
Over 50mm




13: Wing nsf  
Chipped  
1 To 5




14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



15: Door nsf  
Dented  
Over 2 UpTo 10mm



16: Door nsf  
Scratched  
Over 25mm Not Thru Paint



17: Door nsr  
Dented  
2 Or Less UpTo 10mm



18: Door nsr  
Chipped  
1 To 5



19: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



20: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



21: Wheel nsr  
Scratched  
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK