



VEHICLE INSPECTION REPORT

LT61YCX

Mazda 6 2.0 TS2 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	08/09/2011	Body Style	Hatchback	Last service miles	128,707
Year	2011	Keys	2	CAP Clean	£1,075.00
Mileage	132,765 Miles Warranted	Service history	Yes	CAP Average	£670.00
Fuel Type	Petrol	Service documents	Printout	CAP Below	£300.00
Colour	Red	Number of stamps	6	Gearbox	MANUAL
VIN	JMZGHA4E601481495	Last service date	21/08/2024	Doors	5

£65 ADDITIONAL FEE. Last Service: 21/08/2024 at 128707 miles. (6 services (1 main dealer)) Can't open boot latch broken and slight tapping/vibration from engine
Steering feels heavy

Tyres

NSF	GOODYEAR	4.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	4.0mm
OSR	LAUFENN	3.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Trip computer
- Electric door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Front fog lights
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Screen Front
Chipped
UpTo 10mm



4: Wing osf
Chipped
1 To 5



5: Wheel osf
Corroded
Light



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osr
Chipped
1 To 5



8: Qtr Panel osr
Chipped
1 To 5



9: Wheel osr
Corroded
Light



10: Bumper Rear
Cracked
UpTo 25mm



11: Boot Lid
Chipped
1 To 5



12: Qtr Panel nsr
Chipped
1 To 5



13: Wheel nsr
Corroded
Light



14: Door nsr
Chipped
1 To 5

No Image



15: Door nsf
Scratched
UpTo 25mm Not Thru Paint

16: Wing nsf
Chipped
1 To 5



17: Wheel nsf
Corroded
Light

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK