



# VEHICLE INSPECTION REPORT

AK12ZBX

## Ford Fiesta 1.25 Zetec 5dr [82]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama  
GRADE  
4

### Details

Reg. date	28/05/2012	Keys	2	CAP Clean	£1,900.00
Year	2012	Service history	Yes	CAP Average	£1,450.00
Mileage	79,131 Miles Warranted	Service documents	Service Book	CAP Below	£1,025.00
Fuel Type	Petrol	Number of stamps	11	Gearbox	MANUAL
Colour	WHITE	Last service date	22/07/2024	Gears	5
VIN	WF0JXXGAJJCG40924	Last service miles	70,464	Doors	5
Body Style	Hatchback	MOT Due	26/07/2026		

£65 ADDITIONAL FEE

Last service 22/07/2024 at 2024 miles- 11 services (6 main dealer)

No V5

Tyres		
NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	FARROAD	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Cracked  
UpTo 25mm



3: Bumper Front Moulding  
Broken  
Replace




4: Wheel nsf  
Scratched  
Up To 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Chipped  
1 To 5



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Chipped  
1 To 5

No Image



9: Door nsr  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
With Paint Damage



12: Bumper Rear  
Poor Previous Repair  
Poor Colour

No Image



13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint


14: Qtr Panel osr  
Dented  
With Paint Damage



15: Wheel osr  
Scratched  
Over 50mm




16: Door osr  
Chipped  
1 To 5



17: Door osr  
Scratched  
Over 25mm Not Thru Paint



18: Door osf  
Chipped  
1 To 5



19: Door osf  
Scratched  
Over 25mm Not Thru Paint



20: Wheel osf  
Scratched  
Over 50mm

No Image

21: Wing osf  
Scratched  
Over 25mm Not Thru Paint

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

### Vehicle Inspection Report

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK