



VEHICLE INSPECTION REPORT

LP65KWB

Smart Forfour 1.0 Proxy Premium Plus 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/12/2015	Keys	2	CAP Clean	£3,400.00
Year	2015	Service history	Yes	CAP Average	£2,875.00
Mileage	64,796 Miles Warranted	Service documents	Printout	CAP Below	£2,350.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	BLUE	Last service date	03/07/2024	Gears	5
VIN	WME4530422Y029629	Last service miles	53,051	Doors	5
Body Style	Hatchback	MOT Due	29/11/2025		

Last Service: 03/07/2024 at 53051 miles. (6 services) Noise from brakes/underneath while driving and radio fault Exhaust slightly blowing

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Rear headrests
- Isofix child seat anchor points
- Partial leather seat trim
- Cruise control
- Audio remote control
- Air conditioning
- Solid Paint
- Passenger airbag
- Alloy wheels
- PAS
- Digital radio
- Climate control
- ABS
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsr
Dented
With Paint Damage




8: Qtr Panel nsr
Dented
With Paint Damage




9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Door osr
Chipped
1 To 5

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Dented
Between 10mm + 30mm



18: Wing nsf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK