



# VEHICLE INSPECTION REPORT

**EK11NZM**

## Ford Kuga 2.0 TDCi 163 Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/07/2011	Keys	1	CAP Clean	£1,275.00
Year	2011	Service history	Yes	CAP Average	£880.00
Mileage	128,255 Miles Warranted	Service documents	Printout	CAP Below	£475.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	06/09/2024	Gears	6
VIN	WF0RXXGCDRBL71043	Last service miles	124,480		
Body Style	Estate	MOT Due	17/06/2026		

£100 ADDITIONAL FEE LAST SERVICE 6/9/24 @ 124,480 MILES (2 SERVICES) BOOK AND PRINT Bonnet catch broke

### Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing osf  
Scratched  
Over 25mm Thru Paint



4: Wheel osf  
Scratched  
Over 50mm



5: Door osf  
Scratched  
Over 25mm Thru Paint



6: Door osr  
Scratched  
Over 25mm Thru Paint



7: Wheel osr  
Scratched  
Over 50mm



8: Qtr Panel osr  
Dented  
Over 30mm





9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



12: Door nsr  
Scratched  
Over 25mm Thru Paint



13: Door nsf  
Scratched  
Over 25mm Thru Paint



14: Wheel nsf  
Scratched  
Over 50mm



15: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



16: Roof  
Scratched  
Over 25mm Thru Paint



17: Headrest Assy Rear Seat os  
Missing  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK