



VEHICLE INSPECTION REPORT

AP65GYR

Land Rover Discovery Sport 2.0 TD4 180 HSE Luxury 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/12/2015	Keys	2	CAP Clean	£7,400.00
Year	2015	Service history	Yes	CAP Average	£6,475.00
Mileage	76,780 Miles Warranted	Service documents	Printout	CAP Below	£5,500.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	14/12/2020	Gears	9
VIN	SALCA2AN7GH579668	Last service miles	44,151		
Body Style	Estate	MOT Due	04/06/2026		

Last service 14/12/2020 at 44,151 miles- 2 main dealer services Eml light is on

Tyres

NSF	PIRELLI	5.0mm
NSR	BUDGET	6.0mm
OSF	LANVIGATOR	5.0mm
OSR	PIRELLI	7.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm

8: Qtr Panel nsr
Dented
Over 30mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



11: Lamp nsr
Broken
Replace



12: Bumper Reflector nsr
Broken
Replace



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Scratched
UpTo 25mm Thru Paint



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Screen Front
Cracked
Replace



19: Roof
Dented
Over 30mm



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK