



VEHICLE INSPECTION REPORT

RK56XHW

Nissan X-Trail 2.5 16v Aventura 5dr Auto

Cat: C
Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date 01/09/2006

Year 2006

Mileage 110,674 Miles
Warranted

Fuel Type Petrol

Colour BLACK

VIN JN1TBNT30U0124348

Body Style Estate

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 6

Last service date 25/03/2019

Last service miles 84,999

MOT Due 15/10/2025

CAP Clean £1,275.00

CAP Average £920.00

CAP Below £525.00

Gearbox AUTOMATIC

Gears 4

Category C Insurance Loss. Vehicle Extensively Damaged But Repairable -Insurer Decided Not To Repair. VIC PASS: V5 states 'substantially repaired and/or accident damaged: identity checked on 10/12/2010'. Last service 25/03/2019 at 84,999 miles- 6 services (3 main dealer)

Service history is book and print

Tyres

NSF HANKOOK 2.0mm

NSR CONTINENTAL 4.0mm

OSF HANKOOK 3.0mm

OSR HANKOOK 3.0mm

Spare

Features


- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Navigation system
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear electric windows
- ABS
- Central locking
- PAS
- Radio/CD
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Dented
With Paint Damage



12: Qtr Panel osr
Poor Previous Repair
Poor Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
Multiple Chips



15: Door osf
Dented
With Paint Damage



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Over 50mm



18: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		