

## **VEHICLE INSPECTION REPORT**

PG10HZV

## Fiat 500 1.2 Pop 2dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	24/04/2010	Keys	2	CAP Clean	£1,100.00
Year	2010	Service history	Yes	CAP Average	£700.00
Mileage	122,239 Miles Warranted	Service documents	Service Book	CAP Below	£325.00
		Number of stamps	4	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	23/10/2024	Gears	5
Colour	GREY	Last service miles	120,194		
VIN	ZFA31200000503643	MOT Due	22/10/2025		
Body Style	Convertible		,		

LAST SERVICE 23/10/24 @ 120,194 MILES (4 SERVICES 2 MAIN DEALER) BOOK AND PRINT Coolant and oil leak

Radios doesn't work

#### **Tyres**

NSF	BUDGET	4.0mm	
NSR	DUNLOP	4.0mm	
OSF	BUDGET	4.0mm	
OSR	DUNLOP	5.0mm	
Spare			

#### **Features**

- PAS
- FASElectric sunroofFront head restraintsPassenger airbagAlloy wheels

- Steering wheel mounted controls
  Air conditioning
  Rear headrests
  Body coloured bumpers
  Climate control
  Solid Paint

- Central locking


- Remote central locking
- · Electric door mirrors
- · Front electric windows
- Drivers airbag
- Leather seat trim

#### **Photos**










## **Condition Check**



## **Damage Photos**



1: Bumper Rear Scratched Up To 25mm Thru Paint



2: Bumper Rear Scratched 25 to 100mm Thru Paint

# No Image

3: Boot Lid Scratched Over 25mm Not Thru Paint



5: Sill os Dented With Paint Damage



4: Qtr Panel osr Dented With Paint Damage



6: Door osf Dented Over 2 UpTo 10mm

# No Image

7: Door osf Dented Over 2 UpTo 10mm

# No Image

8: Door osf Scratched Over 25mm Not Thru Paint



9: Wing osf Dented With Paint Damage



10: Bonnet Chipped Multiple Chips



11: Bumper Front Scratched 25 to 100mm Thru Paint



12: Bumper Front Scratched UpTo 25mm Thru Paint



13: Wing nsf Chipped 1 To 5



14: Door nsf Dented Over 2 UpTo 10mm

# No Image

15: Door nsf Scratched Over 25mm Not Thru Paint



17: Qtr Panel nsr Dented With Paint Damage



19: Other N/A N/A



16: Sill ns Dented 2 Or Less UpTo 10mm



18: Other N/A N/A



20: Switches And Controls Broken Replace

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	ОК	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK