



VEHICLE INSPECTION REPORT

HV68SVX

Ford Mondeo 2.0 TDCi Titanium Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/09/2018	Keys	2	CAP Clean	£3,300.00
Year	2018	Service history	Yes	CAP Average	£2,775.00
Mileage	145,518 Miles Warranted	Service documents	Service Book	CAP Below	£2,225.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	MANUAL
Colour	SILVER	Last service date	08/01/2025	Gears	6
VIN	WF0EXXWPCEJP32481	Last service miles	135,717	Doors	5
Body Style	Hatchback	MOT Due	09/08/2026		

Last service 08/01/2025 at 135717 miles (9 main dealer services).

Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	2.0mm
OSF	NEXEN	2.0mm
OSR	DAVANTI	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Side airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Scratched
Over 50mm

No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
2 Or Less UpTo 10mm

No Image

7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint




13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Not Thru Paint




17: Door osf
Dented
Over 2 UpTo 10mm



18: Screen Front
Chipped
UpTo 10mm



19: A Post os
Chipped
1 To 5



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK