



VEHICLE INSPECTION REPORT

LF21CLP

Kia Niro 1.6 GDi Hybrid 4 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	23/06/2021	VIN	KNACC81CVM5470236	CAP Average	£10,350.00
Year	2021	Body Style	Estate	CAP Below	£9,150.00
Mileage	99,493 Miles Warranted	Keys	1	Gearbox	SEMI AUTO
Fuel Type	Hybrid Electric	MOT Due	22/06/2026	Gears	6
Colour	BLACK	CAP Clean	£11,550.00		

£100 ADDITIONAL FEE.


Tyres

NSF	NANKANG	3.0mm
NSR	TOYO	5.0mm
OSF	BUDGET	5.0mm
OSR	TOYO	2.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



4: Wing osf
Chipped
1 To 5

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel osf
Scratched
Over 50mm



6: Door osf
Scratched
Over 25mm Thru Paint




7: Door osr
Chipped
1 To 5

No Image

8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Chipped
1 To 5



10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Boot Lid
Chipped
1 To 5

No Image



16: Qtr Panel nsr
Dented
With Paint Damage

15: Boot Lid
Scratched
Over 25mm Not Thru Paint



17: Wheel nsr
Scratched
Over 50mm



18: Door nsr
Scratched
Over 25mm Thru Paint



19: Door nsf
Chipped
1 To 5

No Image

20: Door nsf
Scratched
Over 25mm Not Thru Paint



21: Wing nsf
Chipped
1 To 5



22: Wheel nsf
Scratched
Over 50mm



23: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour Yes

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		