



VEHICLE INSPECTION REPORT

FM17XBJ

Ford B-Max 1.0 EcoBoost Titanium Navigator 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/08/2017	Body Style	MPV	Last service miles	10,510
Year	2017	Keys	2	CAP Clean	£5,100.00
Mileage	11,896 Miles Warranted	Service history	Yes	CAP Average	£4,375.00
Fuel Type	Petrol	Service documents	Service Book	CAP Below	£3,625.00
Colour	Blue	Number of stamps	4	Gearbox	MANUAL
VIN	WF0KXXERJKHR84199	Last service date	30/05/2024	Doors	5

Last service 30/05/2024 @ 10510 miles (4 MAIN DEALER SERVICES)

Tyres

NSF	GOODYEAR	Worn
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- PAS
- Telephone
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Rear airbags
- Central locking
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Screen Front
Chipped
UpTo 10mm



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm




7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Bumper Rear
Scratched
Over 25mm Not Thru Paint




9: Wheel osr
Scratched
Up To 50mm



10: Door osr
Scratched
Over 25mm Not Thru Paint




11: Door osf
Chipped
1 To 5



12: Wing osf
Chipped
1 To 5



13: Wheel osr
Scratched
Over 50mm



14: Tyre nsf
Worn
Replace

No Image

15: Tyre nsf
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK