

VEHICLE INSPECTION REPORT

GY14VXW

BMW 5 Series 520d SE 4dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
4

Details

Reg. date	30/05/2014	VIN	WBA5C32090D606415	CAP Average	£3,950.00
Year	2014	Body Style	Saloon	CAP Below	£3,425.00
Mileage	101,029 Miles Warranted	Keys	1	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	30/10/2025	Gears	8
Colour	BLACK	CAP Clean	£4,475.00	Doors	4

£100 ADDITIONAL FEE.

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Navigation system
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Boot Lid
Scratched
Over 25mm Not Thru Paint



2: Bumper Rear
Scratched
Over 100mm Thru Paint



3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



4: Wheel osr
Scratched
Over 50mm




5: Door osr
Poor Previous Repair
Poor Paint



6: Door osf
Poor Previous Repair
Poor Paint



7: Screen Front
Chipped
UpTo 10mm




8: Wing osf
Scratched
Over 25mm Not Thru Paint



9: Wheel osf
Scratched
Over 50mm




10: Bumper Front
Poor Previous Repair
Poor Paint



11: Bonnet
Chipped
1 To 5



12: Wing nsf
Chipped
1 To 5




13: Wing nsf
Scratched
Over 25mm Not Thru Paint



14: Wheel nsf
Scratched
Up To 50mm



15: Door nsf
Chipped
1 To 5



16: Door nsf
Scratched
Over 25mm Not Thru Paint



17: Door nsr
Chipped
Multiple Chips



18: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm




19: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



20: Wheel nsr
Scratched
Over 50mm



21: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



22: Roof
Dented
Between 10mm + 30mm



23: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK