



VEHICLE INSPECTION REPORT

KN69YFK

Audi Q3 35 TFSI S Line 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	23/09/2019	VIN	WAUZZZF39K1068049	CAP Average	£17,750.00
Year	2019	Body Style	Estate	CAP Below	£16,400.00
Mileage	40,380 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Petrol	MOT Due	22/09/2025	Gears	7
Colour	GREY	CAP Clean	£19,150.00		

£100 ADDITIONAL FEE.


Tyres		
NSF	TOYO	5.0mm
NSR	TOYO	5.0mm
OSF	TOYO	5.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bonnet
Chipped
1 To 5




4: Wheel nsf
Scratched
Up To 50mm




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Dented
2 Or Less UpTo 10mm



10: Door nsr
Dented
2 Or Less UpTo 10mm




11: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint




14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Dented
Over 30mm



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK